



IBM Dealer Confidential

GSMH-39GCEY

Doc Size 1.698 bytes

Service Hints & Tips

IBM PS/2 - 9576i Will Not Power Up

Symptom:

Power Supply internal component can fail after short period of use.

Problem Isolation Aids:

Examine power supply.

Visual Inspection:

With cover on, Magnetek Power supply has Air Vents at the top right hand corner which can be seen through the right hand system loaves. With the System cover off, there is a Vendor Label on the fan openside of the power supply clearly displaying the vendor name.

DETAILS:

POWER SUPPLY VENDOR - MAGNETEK 118 WATT
IBM P/N 79F3367 (FRU P/N 79F3443) HEADER CODE B1JT1

Fix:

REPLACE WITH FRU - IBM P/N 79F3443

SAS KEYWORDS:

D/T9576 D/T9556 PSY2 POWER
POWER FAILURE 76I

Document Information:

Search Keywords
Hint Category **Retain, Power**
Date Created **12.09.95**
Last Updated **08.05.98**
Revision Date **30.04.99**
Brand **IBM PC**
Product Family **PS/2**
Machine Type **9556, 9576**
Model
TypeModel
Retain Tip (if applicable) **H056835**
Reverse Doclinks and Admin Purposes