



Doc Size 1.729 bytes

IBM Dealer Confidential
Service Hints & Tips

Document Number
GSMH-385H59

IBM PS/2 - "IRQ 00 Not Being Serviced" Errors In Error Log

Symptom:

IBM PS/2 9576i, 9576s, 9577i and 9577s systems may log "IRQ 00 Not Being Serviced" errors in the system error log while copying files from the hardfile to the floppy drive.

Problem Isolation Aids:

None

FIX:

Install Flash BIOS update 7677FLSH.EXE (Rev. 8 G7GT60A).

Obtain the latest PS/2 9576/9577 Flash BIOS please double click here: 

If the failure persists after installing the Flash BIOS update, replace the system board.

SAS KEYWORDS :

PSY2	IBMPC	PSY2ERR	PSY2FDSK
D/T9577	9576	9577	PSY2DSK

Document Information:

Search Keywords
Hint Category **Retain**
Date Created **01.08.96**
Last Updated **08.05.98**
Revision Date **30.04.99**
Brand **IBM PC**
Product Family **PS/2**
Machine Type **9576, 9577**
Model
TypeModel
Retain Tip (if applicable) **H083867**
Reverse Doclinks and Admin Purposes