



IBM Dealer Confidential

GSMH-3EGCT5

Doc Size 1.908 bytes

Service Hints & Tips

PS/2 - 76/77 S Model Configures SCSI HD As 6,1

Symptom:

The 9576 or 9577 system configures the harddisk with a SCSI ID of 6,1 instead of 6,0. A POST error of 1047000 107 may also occur.

Problem Isolation Aids:

1. This tip applies only if the 9576 or 9577 is a Model xUx, xNx, or xTx.
2. This tip applies only if the unit is a 9576s, or 9577s.

Fix:

1. The problem is caused by a failing SCSI adapter. The SCSI adapter, FRU P/N71G3576, should be replaced.
2. If the symptom remains, utilise normal problem determination procedures to isolate the failing FRU or application.

Keywords:

PSY2	D/T9576	D/T9576S	D/T9577S
FUTURE	DOMAIN	PSY2FDSK	PSY2ERR
ID	SCSI		

Document Information:

Search Keywords

Hint Category **Retain, SCSI**

Date Created **25.07.95**

Last Updated **08.05.98**

Revision Date **30.04.2000**

Brand **IBM PC**

Product Family **PS/2**

Machine Type **9576, 9577**

Model

TypeModel

Retain Tip (if applicable) **H126789**

Reverse Doclinks and Admin Purposes